

BOROUGH OF HIGH BRIDGE STREETS

July 28,2005

ROAD NAME		Rank	Width	Length		Area	Pav't	Pavement Condition					Traffic	Curbs	SW	Recom	Budget	Field Comments
		Total	Feet	Miles	Feet	Sq. Yds.	Type	Ride	Struct	Crack	Patch	Drain				Improv	Est	
Van Syckle Place	Main St. West to end	34	35	0.042	221	859	Macadam	P	P	G2	P2	X	5	YES	NO	RES-1	\$32,500	
Center Street	Van Syckle Pl to McDonald St	32	20	0.070	370	822	Macadam	P	P	G2	P2		3	NO	NO			Resurfaced 1991
Academy Street		31	18	0.066	350	700	Macadam	P	P	G2	U2		2	NO	NO	RES-2	\$34,000	
Liberty Street		30	18	0.047	250	500	Macadam	P	PF	G2	P2		2	NO	NO	RECLA	\$33,800	
Mine Road	Seal St to Cokesbury Rd	30	14	0.473	2500	3889	Macadam	FP	PF	G2	P2	X	5	NO	NO	RECLA	\$262,500	
Old Jerricho Road	Arch St. to Clinton Twp. Line	30	16	0.421	2224	3954	3.5" FABC-2	FP	FP	G2	P2	X	6	NO	NO	RECLA	\$266,900	Resurfaced 1978
Cregar Road	Rt. 513 to Railroad Bridge	27.5	20	0.777	4100	9111	3.5" FABC-2	F	GF	G1	P1	X	10	NO	NO	RES-2	\$442,800	Resurfaced 1978
Cregar Road	Railroad Bridge to Mun Bdry.	27.5	20' to 32	0.343	1811	4918	3.5" FABC-2	F	GF	G1	P1	X	10	NO	NO	RES-2	\$239,000	Resurfaced 1986
Nassau Road	2+50 to Wilson Ave.	26	16	0.625	3300	5867	Macadam	FP	FP	G2	P1	X	3	NO	NO	RECLA	\$396,000	
Arch Street		25	23	0.330	1744	4457	3.5" FABC-2	FG	FG	G1	P1		8	NO	NO	RES-1	\$168,500	Resurfaced 1978
Buffalo Hollow Road	End resurf to mun. bdry line	25	20	0.114	600	1333	Macadam	FP	PF	G2	P1		1	NO	NO	RES-2	\$64,800	
Hart Street		25	14	0.104	550	856	Macadam	FP	FP	G2	P1		2	NO	NO	RES-1	\$32,300	
Church Street	Seal St. to Mountain Ave.	24.5	32	0.095	500	1778	Macadam	F	F	G1	P1		5	NO	NO	RECLA	\$120,000	
Union Avenue		24	20	0.047	250	556	Macadam	FP	FP	G1	P1		2	NO	NO	RES-2	\$27,000	
Van Syckle Place	Center St. to Main St.	23.5	23	0.024	127	325	Macadam	F	F	G1	P1	X	4	YES	NO	RES-1	\$12,300	
Lake Avenue		22.5	18	0.123	650	1300	Macadam	F	F	G1	P1		3	NO	NO	RES-2	\$63,200	
Taylor Street	Columbia Trail to Prospect St.	22.5	18	0.208	1100	2200	Macadam	F	F	G1	P1	X	3	NO	NO	RES-2	\$106,900	
Dewey Avenue	Berrywood La to Michael La	22	26	0.128	675	1950		G	GF	G1	0		10	YES	NO	RES-1	\$73,700	Resurfaced 1986
Center Street	McDonald Street to end (south)	21.5	16-20	0.081	430	860	Macadam	F	F	G1	P1		2	NO	NO			Resurfaced 1991
Jersey Street		21.5	25	0.061	321	892	Macadam	F	F	G1	P1		2	NO	NO	RES-2	\$43,300	
Prospect Street		21.5	18	0.066	350	700	Macadam	F	F	G1	P1	X	2	YES	NO	RES-2	\$34,000	
Walnut Street		21.5	21	0.059	314	733	Macadam	F	F	G1	P1		2	NO	NO	RES-2	\$35,600	
Central Avenue		20.5	16	0.100	530	942	Macadam	F	F	G1	P1		1	NO	NO	RES-1	\$35,600	
Central Avenue		20.5	16	0.136	720	1280	Macadam	F	F	G1	P1		1	NO	NO	RES-1	\$48,400	
Hoffman Road		20.5	33	0.229	1210	4437	Macadam	F	G	G1	P1		4	YES	NO	RES-1	\$167,700	Reconstructed 1976
Cregar Avenue		20	20	0.080	420	933	3.5" FABC-2	FG	F	G1	P1		2	NO	NO	RES-1	\$35,300	Resurfaced 1991
Hillcrest Lane		20	33	0.296	1565	5738	Macadam	FG	G	G1	P1		5	YES	NO	RES-1	\$216,900	Constructed 1971, ss 1980.
MacDonald Street		20	31	0.076	400	1378	3.5" FABC-2	G	F	G0	0		7	YES	YES	RES-1	\$52,100	Resurfaced 1991
Mountain Avenue		18	18	0.066	350	700	Macadam	FG	FG	G1	0		2	NO	NO	RECLA	\$47,300	
Wilson Avenue	Deer Run Rd. to mun bdry line	18	18	0.023	120	240	FABC	G	G	G1	P1		6	NO	NO	RES-2	\$11,700	
Jane Lane		17.5	33	0.157	830	3043	Macadam	F	G	G1	P1		1	YES	NO	RES-1	\$115,000	Constructed 1971, ss 1980.
Mary Jo Crest		17.5	33	0.105	555	2035	Macadam	F	G	G1	P1		1	YES	NO	RES-1	\$76,900	Constructed 1971, ss 1980.
Sunset Drive		17.5	33	0.265	1400	5133	Macadam	F	G	G1	P1		1	YES	NO	RES-1	\$194,000	Constructed 1971, ss 1980, SC 1991
Beavers Street		16.5	23	0.435	2296	5868	2" I-5	GE	FG	G1	0		5	NO	NO			Resurfaced 2002
Center Street	Main Street to Van Syckle Pl.	16	30	0.024	125	417	Mac, 2" I-5	G	F	G0	0		3	NO	NO			Resurfaced 2004
Wilson Avenue	River Rd. to Watergate Dr.	16	16	0.162	855	1520	2" I-5	EG	F	G0	0		6	NO	NO			Resurfaced 1978; 2002
Woodland Terrace		16	33	0.328	1730	6343	Macadam	FG	GE	G2	P1		1	YES	NO	RES-1	\$239,800	Constructed 1971
New Street		15.5	28	0.066	350	1089	Macadam	GF	GF	G1	P1		1	YES	N	RES-1	\$41,200	Needs water main replaced
Larrison Road		15	29	0.051	270	870	3.5" FABC-2	G	GE	G	0		2	NO	NO	RES-1	\$32,900	Resurfaced 1991
Mill Street		15	20	0.133	700	1556	3.5" FABC-2	G	EG	G0	0	X	7	NO	NO	RES-1	\$58,800	Resurfaced 1978
River Road		14.5	20	0.576	3040	6756	3.5" FABC-2	GE	GE	G0	0		7	NO	NO			Resurfaced 1996
Thomas Street	Church St. to Prospect St.	14.5	33	0.138	730	2677	3.5" FABC-2	GE	G	G0	0		6	NO	NO			Resurfaced 1991
Washington Avenue	Macdonald St. to S. Br Rar R	14.5	24' to 33	0.208	1100	3675	3.5" FABC-2	GE	GE	G0	0		7	YES	YES	RES-1	\$138,900	Resurfaced 1984
Washington Avenue	S. Branch to Tisco Avenue	14.5	32	0.303	1600	5689	3.5" FABC-2	GE	GE	G0	0		7	YES	YES	RES-1	\$215,000	Resurfaced 1986
Washington Avenue	Tisco Ave. to Wilson Ave.	14.5	22	0.232	1225	2994	3.5" FABC-2	GE	GE	G0	0		7	NO	NO	RES-1	\$113,200	Resurfaced 1986
West Main Street	31+50 to Bridge St.	14.5	21	0.042	220	513	3" FABC-2	GE	GE	G0	0		7	NO	NO	RES-1	\$19,400	Resurfaced 1996
Valley View Road	Lake Avenue to Jane Lane	14	21	0.165	870	2030	3.5" FABC-2	G	G	G0	0		4	NO	NO	RES-1	\$76,700	Resurfaced 1991
Valley View Road	Jane Lane to 890'East	14	20	0.169	890	1978	3.5" FABC-2	G	G	G0	0		4	NO	NO	RES-1	\$74,800	Resurfaced 1983
Mine Road	CR 513-Seal St.	13.5	16	0.167	880	1564	I-5 Variable Th.	GE	G	0	0		5	NO	NO			Resurfaced 2000
Water Tank Access Road		13.5	12	0.030	160	213	3.5" FABC-2	GF	G	G1	0		1	NO	NO	RES-1	\$8,064	
Hickory Circle		13	20	0.149	785	1744	Bitum conc	EG	EG	G0	0		8	NO	NO			Constructed 1980
Dennis Avenue		12.5	20' to 40	0.173	915	2033	3.5" FABC-2	GE	G	G0	0		4	NO	NO	RES-1	\$76,800	Resurfaced 1984

BOROUGH OF HIGH BRIDGE STREETS

July 28,2005

ROAD NAME		Rank	Width	Length		Area	Pav't	Pavement Condition					Traffic	Curbs	SW	Recom	Budget	Field Comments
		Total	Feet	Miles	Feet	Sq. Yds.	Type	Ride	Struct	Crack	Patch	Drain			Improv	Est		
Dewey Avenue	Washington Ave. to Manning Ct.	12.5	33	0.227	1196	4385	5" I-2, 2" I-5	E	E	G0	0		10	YES	YES			Reconstructed 2000
Dewey Avenue	Manning Ct. to Berrywood Lane	12.5	28	0.202	1067	3320	5" I-2, 2" I-5	E	E	G0	0		10	YES	YES			Reconstructed 2002
Ridge Road		11.5	21	0.199	1050	2450	3.5" FABC-2	GE	GE	G1	0		3	NO	NO	RES-1	\$92,600	Resurfaced 1979
Sylvan Road		11.5	24	0.265	1400	3733	3.5" FABC-2	GE	GE	G1	0		3	NO	NO	RES-1	\$141,100	Resurfaced 1984
Buffalo Hollow Road	Hickory Cir. to end resurf.	10.5	20	0.322	1700	3778	2" I-5	GE	G	G0	P1		1	NO	NO			
Cokesbury Road		10.5	22	0.143	755	1846	4" Recl, 3" I-2, 2" I-5	E	E	G0	0		8	NO	NO			Reclaimed 2004
Cregar Road	Rt. 513 to Silverthorne Rd	10.5	22	0.024	125	306	4" Recl, 3" I-2, 2" I-5	E	E	G0	0		8	NO	NO			Reclaimed 2004
Silverthorne Road		10.5	22	0.303	1600	3911	4" Recl, 3" I-2, 2" I-5	E	E	G0	0		8	NO	NO			Reclaimed 2004
West Main Street	16+25 to 31+50	10.5	22	0.289	1525	3728	2" FABC	E	E	G0	0		8	NO	NO			Resurfaced 1978, 2005
West Main Street	0+0 (Cregar Rd.) to 1+70	10.5	24	0.032	170	453	Bitum Conc	E	E	G0	0		8	NO	NO			Reconstructed with Cregar Rd bridge
West Main Street	1+70 TO 16+25	10.5	22	0.276	1455	3557	2" FABC	E	E	G0	0		8	NO	NO			Resurfaced 2005
Berrywood Lane		9.5	33		1550	5683	5" I-2,2" I-5	GE	EG	G0	0		3	YES	NO			
Stillwell Road		9.5	33	0.193	1021	3744	Bituminous concrete	GE	GE	G1	0		1	Y	NO	RES-1	\$141,500	
Woodglen Drive		9.5	32	0.065	342	1216		GE	GE	G1	0		1	Y	NO	RES-1	\$46,000	
Church Street	Fairview Ave to Seal St.	8.5	33	0.214	1130	4143	5" I-2, 2" I-5	E	E	G0	0		6	YES	YES			Reconstructed 1996
East Main Street	0+0 to 12+0	8.5	28	0.227	1200	3733	5" I-2, 2" I-5	E	E	G0	0		6	YES	YES			Reconstructed 1987
East Main Street	12+0 to 26+0	8.5	20	0.265	1400	3111	5" I-2, 2" I-5	E	E	G0	0		6	YES	NO			Reconstructed 1987
East Main Street	25+70 to 37+80	8.5	20	0.223	1180	2622	3.5" FABC 2	E	E	G0	0		6	YES	NO			Resurfaced, curbed 2000
Main Street - North		8.5	31	0.084	445	1533	3.5" FABC-2	GE	GE	G0	0		1	1-SIDE	1-SIDE			Resurfaced 1978; curb, SW
Solitude Village	Village Square	8.5	22	0.131	694	1696	Bituminous concrete	E	GE	G0	0		4	YES	NO			Repaired 2003
Solitude Village	Deer Run Drive	8.5	22	0.251	1325	3239	Bituminous concrete	E	G	G0	0		3	YES	NO			
Solitude Village	Pleasant Road	8.5	22	0.273	1442	3525	Bituminous concrete	E	G	G0	0		3	YES	NO			
Tisco Avenue		8.5	20	0.280	1480	3289	3.5" FABC-2	E	GE	G2	0		2	NO	NO			Resurfaced 1991
Wilson Avenue	Watgate Dr. to Deer Run Rd.	8.5	20	0.290	1530	3400	5" I-2, 2" I-5	E	E	G0	0		6	NO	NO			Reconstructed 1994
Solitude Village	Watgate Drive	7.5	22	0.142	750	1833	Bituminous concrete	E	EG	G0	0		4	YES	NO			Repaired 1998
Solitude Village	Greenwich Drive	7.5	22	0.108	568	1388	Bituminous concrete	E	GE	G0	0		3	YES	NO			Repaired 2003
Solitude Village	King Hill Drive	7.5	22	0.249	1313	3210	Bituminous concrete	E	GE	G0	0		3	YES	NO			Repaired 2003
Solitude Village	Mark Drive	7.5	22	0.245	1296	3168	Bituminous concrete	E	GE	G0	0		3	YES	NO			Repaired 2003
Solitude Village	Northwood Drive	7.5	22	0.360	1900	4644	Bituminous concrete	E	GE	G0	0		3	YES	NO			Repaired 2003
Solitude Village	Squire Lane	7.5	22	0.090	475	1161	Bituminous concrete	E	G	G0	0		2	YES	NO			
Highland Ave/Elm St.	6+40-25+50	7	26/32	0.346	1825	5432	4" I-2,2" I-5	EG	E	G0	0		3	YES	NO			Reconstructed 1992
Nassau Road	Highland Ave. to 2+50	7	20	0.047	250	556	4" I-2, 2" I-5	EG	E	G0	0		3	YES	NO			Reconstructed 1992
Solitude Village	High Court	6.5	22	0.098	520	1271	Bituminous concrete	E	G	G0	0		1	YES	NO			
Fine Road		5.5	20	0.505	2665	5922	4" I-2,2" I-5	E	E	G0	0		3	PART	NO			Reconstructed 1990/1
Seal Street		5.5	32	0.098	515	1831	4" I-2, 2" I-5	E	E	G0	0		3	YES	YES			Reconstructed 2003

BOROUGH OF HIGH BRIDGE STREETS

July 28,2005

ROAD NAME		Rank	Width	Length		Area	Pav't	Pavement Condition					Traffic	Curbs	SW	Recom	Budget	Field Comments
		Total	Feet	Miles	Feet	Sq. Yds.	Type	Ride	Struct	Crack	Patch	Drain		YES	NO	Improv	Est	
Solitude Village	Overlook Drive	5.5	22	0.167	880	2151	Bituminous concrete	E	GE	G0	0		1	YES	NO			Repaired 2003
Taylor Street	Mine Rd. to Church St.	5.5	32	0.086	452	1607	4" I-2, 2" I-5	E	E	G0	0		3	YES	YES			Reconstructed 2003
Taylor Street	Church to Col. Trail	5.5	22	0.038	200	489	3" I-2	E	E	G0	0		3	YES	NO			Resurfaced 1997
Thomas Street	Mine Road to Church Street	5.5	32	0.104	550	1956	4" I-2, 2" I-5	E	E	G0	0		3	YES	YES			Reconstructed 2003
MacArthur Street		4.5	26	0.341	1800	5200	4" I-2,2" I-5	E	E	G0	0		2	YES	NO			Reconstructed 1990
Maryland Avenue/Elm Street		4.5	32	0.121	640	2276	4" I-2,2" I-5	E	E	0	0		2	YES	NO			Reconstructed 1995
Patton Street		4.5	26	0.360	1900	5489	4" I-2, @" I-5	E	E	G0	0		2	YES	NO			Reconstructed 1990
Solitude Village	Timberkroft Road	4.5	22	0.189	1000	2444	Bituminous concrete	E	EG	G0	0		1	YES	NO			Repaired 1998
Buffalo Hollow Road	Cregar Rd. to Hickory Cir.	3.5	24	0.063	332	885	6" DGA, 3" I-2, 2" I-4	E	E	G0	0		1	NO	NO			Reconstructed 1994
Manning Court		3.5	28	0.122	645	2007	5" I-2, 2" I-5	E	E	0	0		1	YES	NO			Constructed 1998
Robin Court		3.5	27	0.122	645	1935	5" I-2, 2" I-5	E	E	G0	0		1	YES	NO			Constructed 1988
Solitude Village	Baron Court	3.5	22	0.057	300	733	Bitum conc	E	E	G0	0		1	YES	NO			Improved by Assn.
Wharton Way		3.5	28	0.116	615	1913	5" I-2, 2" I-5	E	E	0	0		1	YES	NO			Constructed 1998
Totals				18.636	98396	255850												

Legend

Pavement Type

B = Bituminous Concrete (Blacktop)
 C = Concrete
 OS = Oil and Stone

Cracks

G0 = few or no cracks
 G1 = moderate cracking
 G2 = many cracks

Patches

0 = few or no patches
 U1 = Moderate utility patches
 U2 = Many utility patches
 P1 = Moderate non-utility patches (potholes)
 P2 = Many non-utility patches

SS Slurry Seat Application
 CS Chip Seal Application

Excellent Condition
 Traffic
 1
 2
 3
 4
 5
 6
 7
 8
 9
 10
 Poor Condition
 Very Busy

Recommended Improvement

RECONS = Reconstruction
 RECLA = Reclamation
 RES-1 = Resurfacing with minor leveling
 RES-2 = Resurfacing with appreciable leveling